


report Number: 0000000703627-EN170
Item location: ALMERE
tour date: 18.08.2020
license plate: TD-816-V

vehicle data

Volkswagen Polo;Hatchback;Diesel;Manual;Silver

| | | | |
|--|--------------------------|------------------------------|--------------------------|
| Vehicle identification number | WVWZZZAWZJY209181 | mileage read: | 72258 km |
| First Registration / construction year: | 13.07.2018 / 0 | Visit Date / place of birth: | 18.08.2020 ALMERE |
| Bodywork: | cars | Body type: | hatchback |
| KBA no. : | null//null | smoking vehicle: | yes |
| state outside: | 2 - Good | condition inside: | 2 - Good |

Damage assessment



1.) Diversen | Wear and tear

comment/reference:

oil loss: in order; instrument cluster: in order; brake system: in order; coupling: in order; engine running: in order; shock absorber: in order; steering test: in Order; transmission: in order; Condition Inside: 2 - Good;

powered by

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



center console



Others



transmission




interior rear



Navigation system



Documentation



1. Diversen

Wear and tear



1. Diversen

Wear and tear



1. Diversen

Wear and tear

general condition: "grade 1,6"

Volkswagen Polo;Hatchback;Diesel;Manual;Silver

First Registration:

13.07.2018

mileage read:

72258

vehicle condition - Average Mark



state - technology

| | |
|--------------------|----------|
| coupling | in order |
| instrument cluster | in order |
| engine running | in order |
| shock absorber | in order |
| transmission | in order |

grading - technology

| | 1 | 2 | 3 | 4 | 5 | 6 | |
|--------------|---|---|---|---|---|---|------|
| brake system | | ✓ | | | | | good |
| oil loss | | ✓ | | | | | good |

grading - Outside

| | 1 | 2 | 3 | 4 | 5 | 6 | |
|------------|---|---|---|---|---|---|------|
| outer body | | ✓ | | | | | good |

grading - Inside

| | 1 | 2 | 3 | 4 | 5 | 6 | |
|-----------|---|---|---|---|---|---|------|
| carpeting | | ✓ | | | | | good |
| coverings | | ✓ | | | | | good |
| cushion | | ✓ | | | | | good |

* Legend rating

| grade | description | definition |
|---------|-----------------------------|---|
| grade 1 | flawless | No defects, dirt, damage or signs of use in terms of appearance and texture. |
| grade 2 | Good condition | Without defects, but with slight signs of wear / dirt as you are unavoidable in normal normal use. |
| grade 3 | Used | With significant signs of use which make a preparation / cleaning necessary. |
| grade 4 | Used condition | Above-average signs of wear and tear that make intensive treatment / cleaning necessary. |
| grade 5 | Condition in need of repair | Used condition with damages such as Burn holes or soiling that requires intensive, professional preparation and repair. |
| grade 6 | Renewable condition | Damage or dirt that makes a replacement necessary. |

General examination

test drive:**Conducted limited**

Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are documented later in the report .

Overview conducted technology audit

oil loss:  in order**brake system:**  in order**engine running:**  in order**steering test:**  in Order**instrument cluster:**  in order**coupling:**  in order**shock absorber:**  in order**transmission:**  in order

Disclaimer Athlon NL