

report Number: 0000000658820-EN170

Item location:ALMEREtour date:30.03.2020license plate:RJ-830-F

## vehicle data

# BMW i3;Hatchback;Electric;Automatic;

Vehicle identification number WBY7Z21030VD74217 mileage read: 42300 km

.:


First Registration / 30.11.2017 / 0 Visit Date / place of birth: 30.03.2020 ALMERE

construction year:

Bodywork: cars Body type: hatchback

KBA no. : null//null smoking vehicle: yes state outside: 2 - Good condition inside: 2 - Good

## Damage assessment



# 1.) Diversen | Wear and tear

#### comment/reference:

oil loss: in order; instrument cluster: in order; brake system: in order; coupling: in order; engine running: in order; shock absorber: in order; steering test: in Order; transmission: in order; Condition Inside: 2 - Good;

powered by



report Number: **0000000658820-EN170** page: 1 from 7



# photographic record



front Left



rear Left



inside



front Right



rear Right



trunk

report Number: **0000000658820-EN170** page: 2 from 7





instrument cluster



center console



Others



mileage



Others



Others

report Number: **0000000658820-EN170** page: 3 from 7





Others



interior rear



Documentation



transmission



Navigation system



1. Diversen

Wear and tear

report Number: **0000000658820-EN170** page: 4 from 7















1. Diversen Wear and tear

page: 5 from 7 000000658820-EN170 report Number:



# general condition: "grade 1,6"

## BMW i3;Hatchback;Electric;Automatic;

First Registration: 30.11.2017 mileage read: 42300



state - technology	
coupling	in order
instrument cluster	in order
engine running	in order
shock absorber	in order
transmission	in order

grading - technology							_
	1	2	3	4	5	6	
brake system		<b>₩</b>					good
oil loss		₩					good

grading - Outside							
	1	2	3	4	5	6	
outer body		<b>₩</b>					good

grading - Inside	_	_	_	_	_		
	1	2	3	4	5	6	
carpeting		<b>₩</b>					good
coverings		<b>₩</b>					good
cushion		V					good

* Legend r	ating	
grade	description	definition
grade 1	flawless	No defects, dirt, damage or signs of use in terms of appearance and texture.
grade 2	Good condition	Without defects, but with slight signs of wear / dirt as you are unavoidable in normal normal use.
grade 3	Used	With significant signs of use which make a preparation / cleaning necessary.
grade 4	Used condition	Above-average signs of wear and tear that make intensive treatment / cleaning necessary.
grade 5	Condition in need of repair	Used condition with damages such as Burn holes or soiling that requires intensive, professional preparation and repair.
grade 6	Renewable condition	Damage or dirt that makes a replacement necessary.

report Number: **0000000658820-EN170** page: 6 from 7



General examination	
test drive:	Conducted limited
	Because of the conditions a short test drive could be performed only at a moderate
	speed . As part of the test drive further tests were carried out. The results are
	documented later in the report .

Overview conducted technology audit							
oil loss:	💜 in order						
brake system:	💜 in order	coupling:	in order				
engine running:	💜 in order	shock absorber:	in order				
steering test:	💜 in Order	transmission:	in order				
instrument cluster:	in order						

Disclaimer Athlon NL

report Number: **0000000658820-EN170** page: 7 from 7