


**report Number:** 0000000709950-EN170  
**Item location:** ALMERE  
**tour date:** 07.09.2020  
**license plate:** HS-073-K

#### vehicle data

#### Toyota Auris;Hatchback;Petrol;Automatic;Blue

Vehicle identification number	<b>SB1MS3JE80E214703</b>	mileage read:	<b>102322 km</b>
First Registration / construction year:	<b>24.12.2015 / 0</b>	Visit Date / place of birth:	<b>07.09.2020 ALMERE</b>
Bodywork:	<b>cars</b>	Body type:	<b>hatchback</b>
KBA no. :	<b>null//null</b>	smoking vehicle:	<b>yes</b>
state outside:	<b>3 - Average</b>	condition inside:	<b>2 - Good</b>

#### Damage assessment



- 1.) tailgate | Wear and tear
- 2.) Door Rear - right | 1 dent
- 3.) Front fender - right | Scratch(es)
- 4.) hood | Scratch(es)
- 5.) Interieur lvs | Burn hole
- 6.) Diverse | Wear and tear

#### comment/reference:

oil loss: in order; instrument cluster: in order; brake system: examined limited; coupling: unavailable; engine running: in order;  
 shock absorber: in order; steering test: in Order; transmission: in order; Condition Inside: 2 - Good;

powered by

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk





instrument cluster



mileage



center console



Others



Others



Others





Others



Others



Others



Others



transmission



interior rear





Navigation system



Documentation



1. tailgate

Wear and tear



1. tailgate

Wear and tear



1. tailgate

Wear and tear



1. tailgate

Wear and tear





1. tailgate

**Wear and tear**



2. Door Rear - right

**1 dent**



2. Door Rear - right

**1 dent**



2. Door Rear - right

**1 dent**



2. Door Rear - right

**1 dent**



3. Front fender - right

**Scratch(es)**






3. Front fender - right

**Scratch(es)**



4. hood

**Scratch(es)**




4. hood

**Scratch(es)**



5. Interieur lvs

**Burn hole**



5. Interieur lvs

**Burn hole**



6. Diverse

**Wear and tear**



6. Diverse

**Wear and tear**



6. Diverse

**Wear and tear**



# general condition: "grade 4,0"


Toyota Auris;Hatchback;Petrol;Automatic;Blue

First Registration:

24.12.2015

mileage read:

102322



state - technology	
instrument cluster	in order
engine running	in order
shock absorber	in order
transmission	in order

grading - technology						
	1	2	3	4	5	6

grading - Outside						
	1	2	3	4	5	6

grading - Inside						
	1	2	3	4	5	6

* Legend rating		
grade	description	definition
grade 1	flawless	No defects, dirt, damage or signs of use in terms of appearance and texture.
grade 2	Good condition	Without defects, but with slight signs of wear / dirt as you are unavoidable in normal use.
grade 3	Used	With significant signs of use which make a preparation / cleaning necessary.
grade 4	Used condition	Above-average signs of wear and tear that make intensive treatment / cleaning necessary.
grade 5	Condition in need of repair	Used condition with damages such as Burn holes or soiling that requires intensive, professional preparation and repair.
grade 6	Renewable condition	Damage or dirt that makes a replacement necessary.

General examination	
test drive:	<p><b>Conducted limited</b></p> <p>Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are documented later in the report .</p>

#### Overview conducted technology audit

<b>oil loss:</b>	✓ in order		
<b>brake system:</b>	✓ examined limited	<b>coupling:</b>	✗ unavailable
<b>engine running:</b>	✓ in order	<b>shock absorber:</b>	✓ in order
<b>steering test:</b>	✓ in Order	<b>transmission:</b>	✓ in order
<b>instrument cluster:</b>	✓ in order		

Disclaimer Athlon NL