


# general condition: "grade 4,0"

## Inname rapport compact

**report Number:** 0000000709950-EN171  
**Item location:** ALMERE  
**tour date:** 07.09.2020  
**license plate:** HS-073-K

**Toyota Auris;Hatchback;Petrol;Automatic;Blue**

**First Registration:** 24.12.2015      **mileage read:** 102322



state - technology	
instrument cluster	in order
engine running	in order
shock absorber	in order
transmission	in order

grading - technology						
	1	2	3	4	5	6

grading - Outside						
	1	2	3	4	5	6

grading - Inside						
	1	2	3	4	5	6

* Legend rating		
grade	description	definition
grade 1	flawless	No defects, dirt, damage or signs of use in terms of appearance and texture.
grade 2	Good condition	Without defects, but with slight signs of wear / dirt as you are unavoidable in normal normal use.
grade 3	Used	With significant signs of use which make a preparation / cleaning necessary.
grade 4	Used condition	Above-average signs of wear and tear that make intensive treatment / cleaning necessary.
grade 5	Condition in need of repair	Used condition with damages such as Burn holes or soiling that requires intensive, professional preparation and repair.
grade 6	Renewable condition	Damage or dirt that makes a replacement necessary.

**General examination**

**test drive:**









**Conducted limited**

Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are documented later in the report .

**reference:**

**Note Road Safe:**

**Overview conducted technology audit**

<b>oil loss:</b>		in order		
<b>brake system:</b>		examined limited	<b>coupling:</b>	 unavailable
<b>engine running:</b>		in order	<b>shock absorber:</b>	 in order
<b>steering test:</b>		in Order	<b>transmission:</b>	 in order
<b>instrument cluster:</b>		in order		

Disclaimer Athlon NL