


report Number: 0000000702482-EN170
Item location: ALMERE
tour date: 18.08.2020
license plate: NT-039-R

vehicle data

Renault Clio;Hatchback;Petrol;Manual;Blue

Vehicle identification number	VF15R240A57139001	mileage read:	99070 km
First Registration / construction year:	21.04.2017 / 0	Visit Date / place of birth:	18.08.2020 ALMERE
Bodywork:	cars	Body type:	hatchback
KBA no. :	null//null	smoking vehicle:	yes
state outside:	3 - Average	condition inside:	3 - Average

Damage assessment



1.) Diverse | Wear and tear

comment/reference:

oil loss: in order; instrument cluster: in order; brake system: examined limited; coupling: in order; engine running: in order; shock absorber: in order; steering test: in Order; transmission: in order; Condition Inside: 3 - Average;

powered by

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



center console



Others



Others



Others




transmission



interior rear



Navigation system



Documentation



1. Diverse

Wear and tear



1. Diverse

Wear and tear



1. Diverse

Wear and tear



1. Diverse

Wear and tear



1. Diverse

Wear and tear



1. Diverse

Wear and tear



1. Diverse

Wear and tear

general condition: "grade 4,0"

Renault Clio;Hatchback;Petrol;Manual;Blue

First Registration:

21.04.2017

mileage read:

99070



state - technology	
coupling	in order
instrument cluster	in order
engine running	in order
shock absorber	in order
transmission	in order

grading - technology						
	1	2	3	4	5	6

grading - Outside						
	1	2	3	4	5	6

grading - Inside						
	1	2	3	4	5	6

* Legend rating		
grade	description	definition
grade 1	flawless	No defects, dirt, damage or signs of use in terms of appearance and texture.
grade 2	Good condition	Without defects, but with slight signs of wear / dirt as you are unavoidable in normal normal use.
grade 3	Used	With significant signs of use which make a preparation / cleaning necessary.
grade 4	Used condition	Above-average signs of wear and tear that make intensive treatment / cleaning necessary.
grade 5	Condition in need of repair	Used condition with damages such as Burn holes or soiling that requires intensive, professional preparation and repair.
grade 6	Renewable condition	Damage or dirt that makes a replacement necessary.

General examination	
test drive:	<p>Conducted limited</p> <p>Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are</p>

documented later in the report .

Overview conducted technology audit

oil loss:	✓ in order		
brake system:	✓ examined limited	coupling:	✓ in order
engine running:	✓ in order	shock absorber:	✓ in order
steering test:	✓ in Order	transmission:	✓ in order
instrument cluster:	✓ in order		

Disclaimer Athlon NL