


report Number: 0000000850325-EN170
Item location: ALMERE
tour date: 09.09.2021
license plate: SN-681-K

vehicle data

Toyota Auris

| | | | |
|---|--------------------------|------------------------------|--------------------------|
| Vehicle identification number | SB1MS3JE60E417878 | mileage read: | 99268 km |
| First Registration / construction year: | 16.05.2018 / 0 | Visit Date / place of birth: | 09.09.2021 ALMERE |
| Bodywork: | cars | Body type: | hatchback |
| KBA no. : | null//null | smoking vehicle: | yes |
| state outside: | 3 - Average | condition inside: | 2 - Good |

Damage assessment



- 1.) Kleurverschil | Wear and tear
- 2.) Diverse | Wear and tear

comment/reference:

oil loss: in order; instrument cluster: in order; brake system: in order; coupling: in order; engine running: in order; shock absorber: in order; steering test: in Order; transmission: in order; Condition Inside: 2 - Good;

powered by

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



center console



Others



transmission



interior rear



Navigation system



Documentation



1. Kleurverschil

Wear and tear



1. Kleurverschil

Wear and tear



2. Diverse

Wear and tear



2. Diverse

Wear and tear



2. Diverse

Wear and tear



2. Diverse

Wear and tear



2. Diverse

Wear and tear



2. Diverse

Wear and tear



2. Diverse

Wear and tear



2. Diverse

Wear and tear

general condition: "grade 1,9"

Toyota Auris

First Registration:

16.05.2018

mileage read:

99268



| state - technology | |
|--------------------|----------|
| coupling | in order |
| instrument cluster | in order |
| engine running | in order |
| shock absorber | in order |
| transmission | in order |









| grading - technology | | | | | | | |
|----------------------|---|---|---|---|---|---|------|
| | 1 | 2 | 3 | 4 | 5 | 6 | |
| brake system | | ✓ | | | | | good |
| oil loss | | ✓ | | | | | good |

| grading - Outside | | | | | | | |
|-------------------|---|---|---|---|---|---|--------------|
| | 1 | 2 | 3 | 4 | 5 | 6 | |
| outer body | | | ✓ | | | | satisfactory |

| grading - Inside | | | | | | | |
|------------------|---|---|---|---|---|---|------|
| | 1 | 2 | 3 | 4 | 5 | 6 | |
| carpeting | | ✓ | | | | | good |
| coverings | | ✓ | | | | | good |
| cushion | | ✓ | | | | | good |

| * Legend rating | | |
|-----------------|-----------------------------|---|
| grade | description | definition |
| grade 1 | flawless | No defects, dirt, damage or signs of use in terms of appearance and texture. |
| grade 2 | Good condition | Without defects, but with slight signs of wear / dirt as you are unavoidable in normal normal use. |
| grade 3 | Used | With significant signs of use which make a preparation / cleaning necessary. |
| grade 4 | Used condition | Above-average signs of wear and tear that make intensive treatment / cleaning necessary. |
| grade 5 | Condition in need of repair | Used condition with damages such as Burn holes or soiling that requires intensive, professional preparation and repair. |
| grade 6 | Renewable condition | Damage or dirt that makes a replacement necessary. |

| General examination | |
|---------------------|--|
| test drive: | <p>Conducted limited</p> <p>Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are documented later in the report .</p> |

| Overview conducted technology audit | | | |
|-------------------------------------|---|----------|---|
| oil loss: |  | in order | |
| brake system: |  | in order | coupling:  in order |
| engine running: |  | in order | shock absorber:  in order |
| steering test: |  | in Order | transmission:  in order |
| instrument cluster: |  | in order | |

The above inspections are carried out without disassembly of parts and/or sheet metal. The bonnet or the front flap, as applicable, is opened for inspection of various components from above. Assessment of the defects found takes place on the basis of the Road Traffic Act, Vehicle Regulations and from the point of view of environmental/safety aspects. Assessment of the vehicle takes place with due regard to the following points; age/mileage/found defects/ overall personal impression of the inspector. Assessment of the inspection items takes place according to criteria and order: Very good / Good / Sufficient / Moderate / Bad / Replace. A limited test drive has taken place. Our vehicles are randomly checked by Tüv Nord. Translated with www.DeepL.com/Translator (free version)