


**report Number:** 0000000849258-EN170  
**Item location:** Almere  
**tour date:** 07.09.2021  
**license plate:** SN-680-K

vehicle data

**Toyota Auris**

Vehicle identification number	<b>SB1MS3JE20E417036</b>	mileage read:	<b>92714 km</b>
First Registration / construction year:	<b>07.09.2021 / 0</b>	Visit Date / place of birth:	<b>07.09.2021 Almere</b>
Bodywork:	<b>cars</b>	Body type:	<b>hatchback</b>
KBA no. :	<b>null//null</b>	smoking vehicle:	<b>yes</b>
state outside:	<b>3 - Average</b>	condition inside:	<b>3 - Average</b>

Damage assessment



- 1.) LV matje | Wear and tear
- 2.) Diverse | Wear and tear

**comment/reference:**

oil loss: in order; instrument cluster: in order; brake system: examined limited; coupling: unavailable; engine running: in order; shock absorber: in order; steering test: in Order; transmission: in order; Condition Inside: 3 - Average;

powered by

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk





instrument cluster



mileage



center console



Others



transmission



interior rear



Navigation system



Documentation



1. LV matje

**Wear and tear**



1. LV matje

**Wear and tear**



2. Diverse

**Wear and tear**



2. Diverse

**Wear and tear**





2. Diverse

**Wear and tear**



2. Diverse

**Wear and tear**

# general condition: "grade 1,7"

**Toyota Auris**

First Registration:

07.09.2021

mileage read:

92714



state - technology	
instrument cluster	in order
engine running	in order
shock absorber	in order
transmission	in order

grading - technology							
	1	2	3	4	5	6	
brake system		✓					good
oil loss		✓					good

grading - Outside							
	1	2	3	4	5	6	
outer body		✓					good

grading - Inside							
	1	2	3	4	5	6	
carpeting			✓				satisfactory
coverings		✓					good
cushion		✓					good









**\* Legend rating**

grade	description	definition
grade 1	flawless	No defects, dirt, damage or signs of use in terms of appearance and texture.
grade 2	Good condition	Without defects, but with slight signs of wear / dirt as you are unavoidable in normal normal use.
grade 3	Used	With significant signs of use which make a preparation / cleaning necessary.
grade 4	Used condition	Above-average signs of wear and tear that make intensive treatment / cleaning necessary.
grade 5	Condition in need of repair	Used condition with damages such as Burn holes or soiling that requires intensive, professional preparation and repair.
grade 6	Renewable condition	Damage or dirt that makes a replacement necessary.

**General examination**

<b>test drive:</b>	<p><b>Conducted limited</b></p> <p>Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are documented later in the report .</p>
--------------------	--

**Overview conducted technology audit**

<b>oil loss:</b>		in order		
<b>brake system:</b>		examined limited	<b>coupling:</b>	 unavailable
<b>engine running:</b>		in order	<b>shock absorber:</b>	 in order
<b>steering test:</b>		in Order	<b>transmission:</b>	 in order
<b>instrument cluster:</b>		in order		

The above inspections are carried out without disassembly of parts and/or sheet metal. The bonnet or the front flap, as applicable, is opened for inspection of various components from above. Assessment of the defects found takes place on the basis of the Road Traffic Act, Vehicle Regulations and from the point of view of environmental/safety aspects. Assessment of the vehicle takes place with due regard to the following points; age/mileage/found defects/ overall personal impression of the inspector. Assessment of the inspection items takes place according to criteria and order: Very good / Good / Sufficient / Moderate / Bad / Replace. A limited test drive has taken place. Our vehicles are randomly checked by Tüv Nord. Translated with [www.DeepL.com/Translator](http://www.DeepL.com/Translator) (free version)