

Kenteken	KZ244J
Merk Model	MINI Mini Cooper 1.5 100kW Marylebone Edition
Brandstofsoort	Benzine
Datum deel1	12/30/16

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
10/26/21	106,339	Airco reinigen	
6/17/21	99,097	Remvloeistof	
6/17/21	99,097	Voertuig diagnose	
11/5/20	91,765	Airco reinigen	
11/5/20	91,765	A.P.K.	
11/5/20	91,765	Remblokken achterzijde	
11/5/20	91,765	Voertuig diagnose	
3/26/20	74,617	Band(en)	
3/26/20	74,617	Sleutelbatterij	
10/22/19	74,616	Airco reinigen	
10/22/19	74,616	Bougie	
10/22/19	74,616	Luchtfilter	
10/22/19	74,616	Olie service	
10/22/19	74,616	Onderhoudsbeurt	
10/22/19	74,616	Ruitenwisserblad(en) voorzijde	
4/1/19	59,444	Remvloeistof	
8/31/18	45,596	Remblokken achterzijde	
8/31/18	45,596	Remblokken voorzijde	
4/11/18	36,001	Olie service	
10/9/17	21,888	Band(en)	