

Kenteken	KX211B
Merk Model	BMW 116d EDE 85kW Corporate Centennial Executive
Brandstofsoort	Diesel
Datum deel1	12/16/16

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
11/4/21	144,306	A.P.K.	
11/4/21	144,306	Olie service	
11/4/21	144,306	Remvloeistof	
11/23/20	137,833	A.P.K.	
5/22/20	134,494	Band(en)	
12/30/19	124,062	A.P.K.	
11/19/19	122,124	A.P.K.	
11/19/19	122,124	Brandstoffilter	
11/19/19	122,124	Luchtfiler	
11/19/19	122,124	Olie service	
11/19/19	122,124	Onderhoudsbeurt	
11/19/19	122,124	Remblokken achterzijde	
11/19/19	122,124	Remblokken voorzijde	
11/19/19	122,124	Remvloeistof	
11/19/19	122,124	Ruitenwiserblad(en) achterzijde	
11/19/19	122,124	Ruitenwiserblad(en) voorzijde	
1/30/19	93,692	Olie service	
10/30/18	83,666	Band(en)	
3/27/18	62,823	Brandstoffilter	
3/27/18	62,823	Luchtfiler	
3/27/18	62,823	Olie service	
3/27/18	62,823	Onderhoudsbeurt	
3/27/18	62,823	Ruitenwiserblad(en) achterzijde	
3/27/18	62,823	Ruitenwiserblad(en) voorzijde	
2/13/18	56,594	Band(en)	
9/8/17	33,117	Olie service	
12/20/16	4	Band(en)	